INSTRUCTIONS

3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER	RECORDATION
------------------	-------------

Corner <u>14 HES 579</u> 31N R. 32W P.M.M. Lincoln

ORIGINAL G.L.O. NOTES: 1918

CORNER: Slate stone 34 x 14 x 14 inches, 24" in the ground, marked 14 HES 579 on SW face,


X on top

9" Fir bears N.65°44'E., 18 1/2 lks 8" Fir bears S.41°00'E., 43 1/2 1ks

Mound of stones, 4 ft. base, 2 ft. high, SW of corner

Slate stone 10 x 14 x 14 inches, marked 14 HES 579 on SW face, X on top 14" Fir bears N.66°E., 12.2 feet 10" Fir bears S.41°E., 28.7 feet EVIDENCE FOUND:


Mound of stone, 4 ft. base, .5' high SW of corner



CERTIFICATION shown herein is true and correct. certify the information Robert Employer: Professions Unc.

Office of Clerk and Recorder, County of Kincoln January record" was filed for record on the _ was noted on the cross-index plat and is assigned page No. 1503Ecemer L. Vaugher by Betty L. Conces Coping Official Stepheny book No. 4

Cross Index No. L - 12, 13 T. 31N R. 32W PMM



corner this sheet