CERTIFIÉD CORNER RECORDATION T. 31 N R. 33 W P.M.M. LINCOLN SW 1/16 Found Brass Cap. S85°36'39"E per Cor. Rec. #496 Found Brass Cap, 2645.37 per Cor. Rec. #23 1322.68 1322.68' 2639.96' **MONTANA ZONE 2500** S85°31'10"E S04°48'01"W NAD83 (1999) IFT 1322.18 **GRID BEARINGS AND DISTANCES** 1319.98" Found Aluminum Monument, per Cor. Rec. #3282 S85°25'40"E 2649.56' S85°25'40"E 2631.18' 2643.35 Found Brass Cap. S04°48'01"W 2645.04' per Cor. Rec. #23 Found Aluminum Monument, per Cor. Rec. #10571, S07°33'51"W 3.24' from C₄. N85°16'41"W 1325.15 **LEGEND** S85°07'41"E 2651.04' Found Aluminum Monument, Found Section Corner As Noted per Cor. Rec. #3281 Found BLM Brass Cap Found Quarter Section Corner As Noted Found Center Quarter Corner As Noted Found 5/8" Rebar, per Cor. Rec. #3284 Set 5/8" Rebar With Aluminum Cap, Stamped "J. SMITH 14739LS" CERTIFICATION certify the information shown herein is true and correct rtify that SKETCH OF CORNER LINCOLN Office of Clerk and Recorder, County of . This "corner Sec. 32 record" was filed for PAGE: 11194 Pages: 1 211714 BOOK: CCR CCER'S STATE OF MONTANA LINCOLN COUNTY was noted on the crecorded: 05/29/2008 10:18 KOI: CCER'S , in TAMMY D. LAUER CLERK AND RECORDER book No. BY: KUL FEE: \$0.00 Cross Index No. _ Y-6 _ т. <u>31 N</u>_ r. <u>__33 W</u>__рмм

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

· corner this sheet