
INSTRUCTIONS



3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner _W 1/4 T. 33 N R. 26 W P.M.M. LINCOLN County

FOUND 314" B.L.M. BRASS CAP

15" Douglas Fir 8 15" Douglas	CERTIFICATION I, certify the information shown herein is true and correct.	
Fir		
B **		NOINTAL
* 70.35	<u> </u>	ound Party Chie
20 C C C C C C C C C C C C C C C C C C C	I. Thomas E. Sand certify that this Corner Record of	
25 20034	by me or under my direction Recordation Act" (70-22-101, et	in compliance with the Corner
N83° 34'E	Necordanion Act 710-22-101, et	seq., M.C.A.)
•	Signature of	Surveyor Seal
	Date: 8/5/98 Reg. No.	7975-8 Signif
SKETCH OF CORNER	Employer: Sands Sur	
Office of Clerk and Recorder, County of Junior	This "corner	Sec. Z-33-Z6
record" was filed for record on <u>\(\textit{\textit{G-13-99}} \) \(\text{-13-99} \)</u>		
was noted on the cross-index plat and is assigned page No.	10150 , in	+ -+-+
book No Otal M. Cummum County Office	By DB	-+++
Cross Index No T	PMM	• - corner this sheet