

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

51/4 SEC 2 T. 33 N R. 26 W, P.M.M. LINCOLN County

FOUND 31/4" B.L.M. BRASS CAP

N85°W ADD SET OF COTTONIDOOD	CERTIFICATION 1. certify the information shown herein is true and correct. Signature Ground Party Chief 1. Thomas E. Sands certify that this Corner Record correctly represents a hypnorrified by me or under my direction in compliance with the Corner. Recordation Act." (20.22-101, et seq., M.C.A.) Signature of Surveyor & Seal Date: 8/5/98 Reg. No. 7975-5 Signature
SKETCH OF CORNER	Employer: Sands Surveying, Inc.
Office of Clerk and Recorder, County of Jancoh record' was filed for record on 8-13-98	Sec. 2-33-26
	ng. B. PlB
Cross Index No T.	RPMM • Corner this sheet