

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner SE cor SEC 2 T. 33N R. 26W P.M.M. LINCOLN County

FOUND 3 1/4" BLM BRASS CAP

Ke in a Fort Pole # 670 Spike w. side	CERTIFICATION
be in side who side w	Signature Ground Party Chief Thomas E. Sands certify that this Corner Record correctly represents year the floor by me or under my direction in compliance will the Goor Recordation Act. (70-22-101, et aeg., M.C.A.) Signature of Surveyor & Seal Date: 8/5/98 Reg. No. 7975-S
SKETCH OF CORNER	Employer: Sands Surveying, Inc.
ecord" was filed for record on 8-13-18	This "corner Sec. 2-33-26
	10152, in
Cross Index No.	T PMM • - corner this shee