
INSTRUCTIONS



- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner SW Cor SEC 2 T. 33N R. 26W P.M.M. LINCOLN County

FOUND 314" BLM. BRASS CAP ALUMINUM CAP

9" LARCH # 2	1818 B. Dead B.T. I. certify the information shown herein is true a		IFICATION
	NOULS Morig. B.T.	I,	herein is true and correct.
14" FIR SKETCH OF	BRASS CAP ST. 10"LARCH OLd Stump CORNER	r. Thomas E. Sand certify that this Corner Record c by me or under my direction Recordation Act" [70-22-101] et	orrectly represents with the Corner seq. M.C.A
Office of Clerk and Recorder, Cou	nty of Juncoln	This "corner	Sec. 2-33-26
record" was filed for record on 8-13-98			
was noted on the cross-index plat and is assigned page No. 10153, in book No. County Official			
	Cross Index No T.	R PMM	- corner this sheet