
## INSTRUCTIONS



3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

N14 T. 33 N R. 26 W P.M.M. LINCOLN

FOUND 31/4" ALUMINUM CAP BY 5612-5

6"FIR	CERTIFICATION
140°E, 140°E, 16"FIR 141.04' - ALUM. CAP 12"FIR	Signature Ground Party Cities  I. Thomas E. Sands  certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the Corner Recordation Act" (79-22-101, et seq., M.C.A.) 78  Signature of Surveyor & Seal / 3.7.  Date: 8/5/98 Reg. No. 7975-8
SKETCH OF CORNER	Employer: Sands Surveying, Inc.
Office of Clerk and Recorder, County of Ancord	This "corner Sec. 2-33-26
	10154 in
was noted on the cross-index plat and is assigned page No  book No	nine Les Dels
Cross Index No.	