


INSTRUCTIONS

1. Original and/or subse record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

- CERTIFIED CORNER RECORDATION

Corner Witness Corner Sec. 19 T. 33N R. 26W P.M.M. Lincoln County
 Sec. 24 T 33N R 27W

Found BLM brass cap



SKETCH OF CORNER

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt
 certify that this Corner Record correctly represents work performed
 by me or under by direction in compliance with the "Corner
 Recordation Act" (70-22-101, et seq., M.D.A.)

D.K. Marquardt
 Signature of Surveyor & Seal


Date: 7-28-81 Reg. No. 2580ES

Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner
 record" was filed for record on the July 17th day of 1981 WC
 was noted on the cross-index plat and is assigned page No. 1098, in
 book No. 1

Sharon L. Daugherty by Betty Bell
 County Official Deputy

Sec. 19



• - corner this sheet

Cross Index No. 0-P 1 T. 33N R. 26W P.M.M.
0-P 25 T 33N R 27W