2. Description of evidence found, note discrepancies in the record, state method of establishing

Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Secitor Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Sec. Cor. Sections 19,15,20 :23 T. 330 R. & GOO P.M.M. Lincoln

Found BLM brass cap

