3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

Voltage & fift &

र. १ . ३ ३०० <mark>द्वारत ।..</mark>

Walter Car

CERTIFIED CORNER RECORDATION

1/4 Corner Between Section 19 T. 33N R. 26W P.M.M. Lincoln __County Section 24 T 33N R 27W

This corner was never set by GLO. or BLM.

Set corner by Single proportion between Witness Corners North and South of 1/4 Corner.

> Set standard 2" diam. Aluminum Monument With 3" Cap marked as shown below.

An 8" Spruce mkd. "5 19 BT" bears S50°E 1.98'

A 10" Spruce mkd. "S24BT" bears N18°W 33.50'

SKETCH OF CORNER

t,
certify the information shown herein is true and correct.
Signature Ground Party Chief
I. S. R. Smith
certify that this Corner Record correctly represents work performed
by me or under by direction in compliance with the "Corner
Recordation Act" (70-22-101, et seq., M.D.A.)
SR Smith
Signature of Surveyor & Seni
Date: 1/14/82 Reg. No. 47405
Employer: Smith Surveying Co.
, ,

CERTIFICATION

Office of Clerk and Recorder, County	y of This "corner	Sec. / 9 = 2 4
record" was filed for record on the _	July 28th day of 1987,	
was noted on the cross-index plat an		S14 SH9
book No.	Eleanor L. Vaughn by Betty L. Conces	R27W R26 W
	O L 320/ 220/	

T. <u>33/7</u> R. <u>26W PMM</u> T33N R 27W

corner this sheet