INSTRUCTIONS 1. Original aud/or subsequent record used to evaluate the curner position 2. Description of e

3. Description of monument and accessories set to perpetuate the corner p

4. Savich or corner, show all pertinent data which can best be shown in a sketch example, corner marking. lupography lies, position of accessories, sic.

8. Certification must be signed and sealed by Registered Land Surveyor in State of Mostaas.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

SW 1/16 Sec. 13 Corner __ T. 33N R. 26W P.M.M. LINCOLN _County

No record or evidence of corner being previously set.

I position corner from found Section and Quarter corners and as shown on the Certificate of Survey as filed and as of record in the Lincoln Co. Courthouse.

I set a 3" alum. cap for corner position, from which:

A 7" tamarack bears S.88°E., 2.6' soribed SW 1/16 S13 BT A 9" pine bears S.11" W., 11.3' scribed SW 1/16 S13 BT

Painted red bands around BT's and painted blazes red. Posted BT, Attention, and Location signs. Placed a 6' metal post w/survey monument sticker along side cap.

