## INSTRUCTIONS

ed to evaluate the curner

3. Description of monument and accessories set to perpetuale the corner position.

6. Shelich or corner, show all pertinent date which can best be shown to a shelich example, corner metopography ties, position of accessories, etc.

5. Certification must be signed and sealed by Hegistered Land Surveyor in State of Montans.

6. Fill in Cross ladex & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

SE 1/16 Cor. Sec. 14 T. 33N R. 26W P.M.M. LINCOLN Corner \_\_ \_County


No record or evidence of corner being previously set.

I position corner from found Section and Quarter corners and as shown on the Certificate of Survey as filed and as of record in the Lincoln Co. Courthouse.

I set a 3" alum. cap for corner position, from which:

A 13" fir bears N.41° 30'E., 22.9' scribed SE 1/16 S14 BT A 6" tamarack bears S.1° E., 9.8' soribed SE 1/16 S14 BT

Painted red bands around ET's and painted blazes red. Posted BT, Attention, and Location signs. Placed a 6' metal post w/survey monument sticker along side cap.



CERTIFICATION GLENN KNODLE N certify the information shown begoin is true and correct. GENE WARREN territy that this Corner Record correctly represents work performed by me or under by direction in compilance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

H. Hene Warner Gene Warre Signature of Surveyor & Seal Reg. No. 27345 TAMARLACK Employer: POCKY MOUNTAIN BURNEYORS SKETCH OF CORNER Office of Clerk and Recorder, County of ... LINCOLN Sec. 14 . This "corner record" was filed for record on the NOU 30 \_ day of 19 84 was noted on the cross-index plat and is assigned page No. 2814 County Official Deput book No. deputy

M20

Cruse Indea No. .....

T. 33N R 26W