INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of evidence found, note discrepancies in the record, state flection of evidence found, note discrepancies in the record, state flection of evidence found, note discrepancies in the record, state flection of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner d Cor. Sec. 7 & 8

Original GLO Notes: Set a limestone 20x6x4 in., 15" in ground for 1 Sec. Cor.,

mkd. $\frac{1}{4}$ on West face from which:
A fir 24" bears N41 $\frac{1}{2}$ E 43 lks mkd. $\frac{1}{4}$ S8 BT.
A Tamarack 8" bears S52°W 20 lks mkd. $\frac{1}{4}$ S7 BT.

(1916 by Mans H. Coffin, Jr., R. Fitzhugh Maclean, & James R. Cumming)

Remonumentation Survey: Duane G. Lindenberg, Cadastral Surveyor, 1965. Found GLO limestone 24x6x4 in. firmly set, mkd. $\frac{1}{4}$ on W. Face & witnessed by the original BT's.

At corner point set an iron post, 30" long, $2\frac{1}{2}$ " dia., 26" in ground w/brass cap mkd: T32N₁R30W

S7 IS8 1965

Original BT's: A fir 26" bears N41½°E 43 lks, blaze overgrown. A larch 13" bears S52°W 20 lks, " " .

Found a brass cap 3½", on an iron post mon. (BLM) at corner. Existing BT: 30" fir N41°E 26.7' w/ blaze overgrown. New BT: 10" tamarack N12°W 25.75' mkd. ½ S7 BT.

Built a rock cairn 3' dia. around monument and cleared ground in 6' dia. Painted & signed BT's to meet USFS Specs. Set sign post near corner.

Declination assumed 20°E.

		\	
T32	N F	130W	
	1		1
	i	•	
\ s		S8	
	196	55/	
_		-	

Dennis D. Findarff certify the information shown herein is true and correct. Signature Ground Party Chief Robert E. Findorff or & Seal Date: 9/12/87Reg. No. 3976ES Employer: Self

SKETCH OF CORNER (SEE ABOVE)

0,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Office of Clerk and Recorder, County of Lincoln	This ''corner	Sec. 8	T32N	R30W
record" was filed for record on	3			\vdash
was noted on the cross-index plat and is assigned page No	710, in	+ -+	-+-	
book No County Office	ial Depity			+ +

Cross Index No. <u>G5</u> T. <u>32N</u> R. <u>30W</u> PMM Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

corner this sheet