INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

3. Description of monument and accessories set to perpetuate the corner position.

- Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ites, position of accessories, etc.
 Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

SE 1/16 of Sec. 32 Lincoln Corner . County

- No previous record.
- No evidence found on the ground.

III. At the determined corner position, set a 3/4 in. dia. aluminum rod, 28 ins. long, 24 ins. in the ground with an attached 3 1/4 in. dia., U.S.D.A. Forest Service aluminum cap marked as shown:

> SE 1/16 S32 9008LS 1990

from which

A douglas fir, 10 ins. dia., bears $874^{\circ}E$, 21.4 ft. dist., mkd. SE 1/16 S32 BT. A douglas fir, 8 ins. dia., bears $N25^{\circ}W$, 37.7 ft. dist., mkd. SE 1/16 S32 BT.


Place a collar of stone around monument.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals South, 3 ft.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs

Magnetic Declination: East 19





SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln Sec. . This "corner was noted on the cross-index plat and is assigned page No. book No.

> Cross Index No. PMM

· - corner this sheet