2. Description of evidence found, note discrepancies in the record, state method of establishing ic 3. Description of monument and accessories set to perpetuate the corner position. 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet. CERTIFIED CORNER RECORDATION LINCOLN P.M.M. County 1. CORNER SET BY SINGLE PROPORTION -SET 5/8" REBAR WITH YELLOW PLASTIC CAP STAMPED J.H.N. 4661 S -SET BEARING TREE N 53° 30' W, 32.6 FEET, 8" DOUGLAS FIR SCRIBED S 35 E 1/16 BT -SET BEARING TREE S 50 30' E, 35.8 FEET, 12" DOUGLAS FIR SCRIBED S 2 E 1/16 BT -SET LOCATION POSTER N 48° E, 21.2 FEET, 5" PONDEROSA PINE CERTIFICATION 35 E VIG BT David Stanley SET 5/8" × 24" Jack H. Ninneman CAPPED STEEL PIN certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-10), et seq., M.D.A.) 4/4/83 4661 S Reg. No. 4001 S NINNEMAN ENGINEERING, INC. S2 E 1/6 BT **SKETCH OF CORNER** Sec. Office of Clerk and Recorder, County of LINCOLL . This "corner APRIL :7 record" was filed for record on the _ day of 1933, was noted on the cross-index plat and is assigned page No. _

real but

County Official

· - corner this sheet

book No.