INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

Description of monument and accessories set to perpetuate the corner position

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking 5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Lincoln N 1/16 Section 27 County

Davis Surveying Inc. 1987

I set a $3\frac{1}{4}$ " diam. Aluminum Cap on a 5/8" diam.x 4' long rebar. Cap stamped;



A 5" cedar bears N.45°E. 14.5 feet from the center of tree. Scribed N 1/16 BT. Notched tree at root crown. Painted a red band at 15" 6:2-SURVE N 1/16 BT. Notched tree at root crown. Painted a red band around tree. A 15" fir stump bears N.5 W. 8.9 feet from center of stump. Scribed

N 1/16 BT. Painted stump red. Placed ST. Regis location poster on front of BTs.

> Ken E. Davis certify that this

SKETCH OF CORNER

Office of Clerk and Recorder, County of This "corner record" was filed for record on the day of 1987 was noted on the cross-index plat and is assigned page No book No. Official

Cross Index No. .

Davi

ONTA

KENNETH E DAVIS 4975 S

corner this sheet

k performed