## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner C-N-SW 1/64 Corner Sec. 27 33N R. 27W \_\_\_ P.M.M. \_\_\_ Lincoln County

ORIGINAL G.L.O. NOTES: THIS CORNER WAS NEVER SET

Set 2½" X 30" Aluminum Monument with 3½" cap. Marked as shown.

S 27 C-N-SW 1/64 1981 2520S

SEE CERTIFICATE OF SURVEY NO: 1007 FOR SECTION BREAKDOWN

9" Spruce (3 47.4" Mon. scribed "CNSW 1/64 BT" (NEW)	Signature Ground Party Chief  I. HATGES  certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq. 10.7). A)  Signature of Surveyor & Scal  Date: 12/1981 Reg. No. 25205
SKETCH OF CORNER	Employer:

- corner this sheet

was noted on the cross-index plat and is assigned page No. 1580

book No.

£ \*\*\*\* **4** :