
INSTRUCTIONS

at record used to evaluate the corner position.



Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner_SW-SE-SE1/256_SEC_17_T.__33N____R.__34W___P.M.M.__LINCOLN_____County

1) No records found at Lincoln County Courthouse

No evidence found on the ground 2)

At the corner position as determined by survey, set a 5/8"x 30" rebar, with a $3\frac{1}{4}$ " 31


aluminum cap, marked as shown:



From which:

A 10" Cedar bears N41°W, 9.4' distant, scribed SW SE SE1/256 S17 BT. A 7" Cedar bears N89°E, 12.5' distant, scribed SW SE SE1/256 S17 BT.

Monument was set 0.2' above grade. A 6' steel post with Land Survey Monument and Forest Service Property Boundary decals attached was placed 1' west of monument. Blazes and scribing on bearing trees were painted red. Bearing tree tags and Land Survey monument signs were attached to trees.



Office of Clerk and Recorder, County of fincoln. This "corner record" was filed for record on 5-3-99
record was filed for record on 5-5-77
was noted on the cross-index plat and is assigned page Noin book Noinin

SE% Sec. 17					
			•		

Cross Index No. <u>M.75-8.25</u> T. <u>33N</u> R. <u>34W</u> PMM