
INSTRUCTIONS



- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner N 1/16 sec. 2 & sec. T. <u>33N</u> R. <u>34W</u> P.M.M. <u>Lincoln</u> County

- 1. Record: 5/8 rebar with yellow plastic cap stamped J. H. N. 4661S. COS #1326.
- 2. Found: 5/8 rebar and no bearing trees.
- 3. Accessories: a Larch 14" diam. bears S 72 E 17.40 ft dist. and marked 1/16 S 2 BT.

a Larch 8" diam. bears S 75 W 4.50 FT. dist. marked 1/16 S 3 BT.

CERTIFICATION DAN CROFT ertify the information shows herein is true and correct. SURVEYORS SKETCH OF CORNER Office of Clerk and Recorder, County of _ . This "corner record" was filed for record on the Feb 34 day of 1957 was noted on the cross-index plat and is assigned page No. book No.

Cross Index No. B-17 T. 33 N R. 34 W. PMM

· corner this sheet