## INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

T. \_\_\_\_33 N., R. \_\_\_34 W., P.M.M. 13 of ES 1258 Lincoln Corner\_ \_County 1941 U.S.D.A. F.S. Exchange Survey No. 1258 by Donald Sawhill: "Set an iron post, 3 ft. long,

13 E S 1258


2 in. diam., 26 ins. in the ground, with broken glass deposited at the base, with brass cap marked

The point on the brass cap is the exact cor, point from which

A cross (x) on a white fir, 10 ins. diam., bears  $856^{\circ}20$ 'E, 28 lks. dist. A cross (x) on a white fir, 8 ins. diam., bears  $530^{\circ}30'$ W, 41 lks. dist., each blazed and scribed 13 E S 1258 B T.

Raise a mound of earth 4 ft. base, 2 ft. high, S.E. of corner."

II. Found a 2 in. diam. iron pipe, 8 ins. above ground with 2 1/2 ins. diam. U.S.F.S. brass cap, marked as shown:



No bearing trees found.

Found mound of earth SE. of corner.

III. Established two new bearing trees:


A fir, 10 ins. diam., bears N20 $^{\circ}$ E, 5.7 ft. dist., mkd. 13 ES 1258 BT. A fir, 7 ins. diam., bears S43 $^{\circ}$ E, 15.4 ft. dist., mkd. 13 ES 1258 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, East, 3 ft.

Magnetic Declination: 20 East

book No. .



13 ES 1258

33 N R.

· corner this sheet