INSTRUCTIONS

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ties, position of accessories, etc.


5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill In Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>W 1/16 cor. of Secs. 16 & 21</u> 33 N., R. 34 W., P.M.M. County

- No records found at Lincoln County Courthouse.
- II. No evidence found on the ground.
- III. At the cor. as position determined by survey, set a 3/4 in. diam. X 30 in. long driveable aluminum rod flush with the ground, with a 3 1/4 in. diam. alum. cap mkd. as shown:



from which


A pine, 10 ins. diam., bears N 54° E, 47.9 ft. dist., mkd. W 1/16 S 16 BT. A fir, 7 ins. diam., bears S 71° E, 45.9 ft. dist., mkd. W 1/16 S 21 BT.

Set a 6 ft. galvanized steel guard post with Survey Marker and Property Boundary decals attached, West, 3ft.

Painted red bands around each bearing tree and attached Land Survey Mounument and Bearing Tree signs.

20° East Magnetic Declination:

> GLO - WEST- 40.0 chs. N89° 45' 45" W 1325.73 1325.73



Office of Clerk and Recorder, County of record" was filed for record on .. was noted on the cross-index plat and is as book No. .

T. ____ Cross Index No. .