CERTIFIED CORNER RECORDATION Corner C-N 1/16 Section 36 T. 34N R. 25W P.M.M. LINCOLN County G.L.O. Record: This interior section subdivisional corner was never set by G.L.O. or other original government survey, but its position can be calculated by dimensions shown on the official government plat for this township. Subsequent Record: Certificate of Survey No. 1614, Phil Helps, 4739S. Certificate shows that a 5/8" rebar with plastic ID cap was set at the corner position. Proportional methods used to establish the corner position were verified as correct. Evidence Found and New Monumentation Established: At the calculated position for the corner, as established by proportionate measure and as shown on the attached section subdivisional diagram, I find a 5/8" diameter rebar with a yellow plastic cap stamped "Helps 4739S". I replace the rebar and cap with a Berntsen flared base monument (model #A1NBF30), which consists of a 2-3/8" diameter by 30" long flared aluminum pipe with a magnet and 3-1/4" diameter aluminum cap attached to the top, stamped as shown in detail below. I bury the rebar inside the monument pipe. Top of installed monument is flush with ground. Section Subdivision Section 36, Township 34 North, Range 25 West 21/22001 2638.80* 2649.07 SURI C-N 1/16 4740LS Smith Surveying & Consulting SKETCH OF CORNER Office of Clerk and R 190083 BOOK: CCR CCER'S PAGE: 10884 Sec. 36 record" was filed for STATE OF MONTANA LINCOLN COUNTY RECORDED: 12/05/2005 2:07 KOI: CCER'S was noted on the cri coral M. CUMMINGS CLERK AND RECORDER FEE: \$0.00 BY: TO: SMITH SURVEYING 1131 SOUTH MAIN, P.O.BOX 7323, KALISPELL,

34

T. 35N R. 26W

.РММ 🤄

•=corner this sheet

Cross Index No. W-23

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

1

1777 12 2 17 The state of the s