\CLIENTS\Department_of_State_Londs\Stryker\

CERTIFIED CORNER RECORDATION

Corner N1/16 S36,T34N,R25W & S31,T34N,R24WT. 34N R. 25W P.M.M. LINCOLN County

G.L.O. Record:

This interior section subdivisional corner was never set by G.L.O. or other original government survey, but its position can be calculated by dimensions shown on the official government plat for this township.

<u>Subsequent Record:</u> Certificate of Survey No. 1614, Phil Helps, 4739S. Certificate shows that a 5/8" rebar with plastic ID cap was set at the corner position. Proportional methods used to establish the corner position were verified as correct.


Evidence Found and New Monumentation Established:

At the calculated position for the corner, as established by proportionate measure and as shown on the attached section subdivisional diagram, I find a 5/8" diameter rebar with a yellow plastic cap stamped "Helps 4739S".

I replace the rebar and cap with a Berntsen flared base monument (model #A1NBF30), which consists of a 2-3/8" diameter by 30" long flared aluminum pipe with a magnet and 3-1/4" diameter aluminum cap attached to the top, stamped as shown in detail below. I bury the rebar inside the monument pipe. Corner falls in scree field at the base of a cliff. Raised a large stone mound around monument.

Section Subdivision

Section 36, Township 34 North, Range 25 West






SKETCH OF CORNER

CERTIFICATION Michael R. Rice 4740LS Employer Smith Surveying & Consulting

Office of Clerk and	Recorder County of - 190084 BOOK: CCR	Lincoln	This Compan
	STATE OF MONTANA LINC	OLN COUNTY	<u>-</u>
was noted on the cr	RECORDED: 12/05/2005 CORAL M. CUMMINGS CI	2:08 KOI: CCER'S ERK AND RECORDER	2 Lens Topuly 7323, KALISPELL, MT
book No	FEE: \$0.00	BY: FLERNIE	7323 FALLEDELL ST. DEPULY
		ex No. <u>W-25</u> T.	



Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

