CERTIFIED CORNER RECORDATION Corner C-E-W 1/64th Cor Sec 7 T. 34N R. 25W P.M.M. Lincoln County

1. NONE

2. Found:

A 5/8 ins. rebar with yellow plastic cap mkd. #7328S

Replaced yellow plastic cap with an Aluminum Cap, 3½ ins. diam., on the 5/8 ins. Rebar, 0.2 ft. above ground, mkd. as shown; Established:

A Douglas Fir, 8 ins. in diam., bears S87E, 12.2 ft. dist., scribed "C-E-W 1/64 S7 BT"; A Douglas Fir, 10 ins. in diam., bears S35E, 19.2 ft. dist., scribed "C-E-W 1/64 S7 BT"; Steel posts with decals bear South and East, 2.0 ft. dist.



MAGNETIC DECLINATION - 15°2' EAST

٨		CERTIFICATION	
Steel Posts South and East, 2.0	8" D Fir S87'E, 12.2' 10" D Fir S35'E, 19.2'	LAWRENCE A. CLAHE certify that the Corner Rectification Act of	d Porty Gint Str. A Complete S
SKETCH OF CORNER		Employer GLAHE & ASSOCIA	THE PERSON NAMED IN COLUMN TO THE PE
record" was filed for record (was noted on the cross-inde	STATE OF MONTANA LINCOLN COUNT RECORDED: 12/09/2010 10:46 KG	PAGE: 11686 Pages: 1 Y II: CCER'S RDER 1863, SANDPOINT, ID. 88860,	Sec. 7
Adopted July 1, 1981, Ma	ontana Board of Professional Engineers	& Land Surveyors	corner this sheet

. • .