


INSTRUCTIONS

1. Original and/or subseq. record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner $\frac{1}{4}$ corner Sec. 9 & 10 T. 34N R. 25W P.M.M. Lincoln County

Found BLM brass cap



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

I, DK Macquardt

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

DK Macquardt
Signature of Surveyor & Seal

Date: 10/16/81 Reg. No. 2289ES


Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the February 17th day of 1982 was noted on the cross-index plat and is assigned page No. 1524, in book No. _____

Eleanor L. Hughes by Betty L. Conner
County Official deputy

Cross Index No. G-13 T. 34N R. 25W P.M.M.

Sec. 9



• - corner this sheet

100-100000