INSTRUCTIONS COLUMN 4. Shelch or corner, show all pertinent data which can best be shown in a shelch example, corner marking. ography ties, position of accessories, etc.

5. Certification must be signed and seeied by Registered La. 5. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER	RECORDATION
------------------	-------------

C 1/4 Sec. 31 Corner . T. 34N R. 25W LINCOLN P.M.M. County


No record or evidence of corner being previously set.

I position corner from found section and quarter corners and as shown on the Certificate of Survey as filed and as of record in the Lincoln Co. Courthouse.

I set a 3" alum. cap for commer position, from which:

A 14" pine bears N.75°W., 39.75' scribed C 1/4 S31 BT An 8" pine bears N.63°W., 6.75' scribed C 1/4 S31 BT

Painted red bands around BT's and painted blazes red. Posted BT, Attention, and Location signs. 6' metal post w/survey monument sticker along side cap.



B" PINE 14" ANE

CERTIFICATION KNODLE rmation shown herein is true and correct. certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner by me or under by direction in com-Gene Wanes

Reg. No. 27345 Employer: Packy Hountain BURNEYORS

SKETCH OF CORNER Office of Clerk and Recorder, County of . LINCOLN . This "corner record" was filed for record on the _ day of 1954 was noted on the cross-index plat and is assigned page No. F Sugal le County Official book No. _

deputy

X-3

- 34N . 25¥

