
- of evidence found, note discrepancies in the record, state method of establishing just or obliterated
- Description of monument and accessories set to perpetuate the corner position.
   Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography fles, position of accessories, etc.
- 5. Contilication must be signed and scaled by Registered Land Surveyor in State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.


## CERTIFIED CORNER RECORDATION

34N Lincoln E 1/16 between Secs.2 & 11 Corner. \_County

- (1) This corner not previously set.
- (3) Set: 3½ in. aluminum cap on a 30in. pipe stamped as shown below from which An 8 in. Doug fir (scribed E 1/16 S2 BT) bears \$ 84 W 6.1 ft. A 6 in. Doug fir (scribed E 1/16 S 11 BT) bears S 190W 23.8 ft. A location poster on an 8 in. Doug. fir bears N 70°W 4.3 ft.

Painted monument and accessories with bright red paint.





Cross Index No.

corner this sheet

CON CONTRACTOR OF THE STATE OF