
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography thes, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

orner <u>C-S 1/16, Sec. 12</u> Lincoln

- This corner was not previously set.
- Set a 3"X30" aluminum capped monument marked as shown below, from which: A 10" Fir bears N 43 E, 13.00 feet, marked "CS 1/16 S-12 BT" and posted. A 5" Fir bears N 21 W, 12.70 feet, marked "CS 1/16 S 12 BT" and posted. I painted the monument and accessories with bright red paint and attached a Land Monument sign to a metal fence post next to the corner.



SIFIF 10"Fir NZIW, N43E, 12.70 13.00 **SKETCH OF CORNER**

CERTIFICATION James R. Staples erilly the Signature Ground Party Jack H. Ninneman certify that this Corner Record correctly represents work performed by one or under by direction in compilance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 11/15/87 Reg. No. 46613 Employer: NINNEMAN ENGINEERING

ce of Clerk and Recorder, County of Huncoln ord" was filed for record on the _______Manak_ day of 1974

noted on the cross-index plat and is assigned page No. # 2507

anet B. F. Sugel by Moren County Official deputy

12

Sec.

C