at to evaluate the corner position. . -

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography thes, position of accessories, etc.

5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

S 1/16, Sec. 12 T. 34 N R. 26 W Lincoln County

1. This corner was not previously set.

Corner

Set a 3"X30" aluminum capped monument marked as shown below, from which: A 11" Douglas Fir bears N 42 58 44 E, 17.10 feet, marked"S 1/16 S 12 BT"and posted. A 6" Larch bears N 46 21 40 W, 19.90 feet, marked"S 1/16 S 12 BT" and posted. I painted the monument and accessories with bright red paint and attached a Land Monument sign to a metal fence post next to the corner.



)) • •