d used to evaluate the corner position

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or


Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

NW 1/16 Sec. 12 corner · 26W P.M.M. County

- 1. This corner was not previously set.
- 2. Set a 3"X30" aluminum capped monument marked as shown below, from which: A 7" pine bears S76 W, 18.35 feet, marked "NW 1/16 S12 BT" and posted. A 6" fir bears S80E, 12.15 feet, marked "NW 1/16 S12 BT" and posted. I painted the monument and accessories with bright red paint, and placed a Land Monument sign on a 6" fir 12' south of the corner.





. . . • • . . · · . . · . .