DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No monument found

found 2 Fir stumps with chop marks that agree with record distance, Bearing Trees:

there is a discrepancy in bearings.

Original Record: A 8" Fir, bears N54°30'W, 7 Lks., marked 1/4 S BT

A 6" Fir, bears N43°45'W, 4 Lks., marked 1/4 S BT

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

1979 Date of work:....

Set a 3" X 30" Aluminum pipe from intersection of distances of original bearing trees (stumps).

Cap is marked as shown:

from which: A 8" Fir, S59°50'W, 13.1 Ft., scribed 1/4 S35 BT A 6" Fir, N25°25'E, 3.4 Ft., scribed 1/4 S36 BT

R26Wi гзим **S35** \$36 **5612S** 1979

Set corner falls within 5.5 Ft. of proportionate point for 4 corner

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 747

Surveyor's Seal



certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Thomas C. Hill certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

T3LN R26W **S35 S36** 

= Corner recorded on the sheet

5612**-**S Registration Number

Office of Clerk and Recorder, County of Lexicals	J
This "corner record" was filed for record on the 3 day of .	March 1980, was noted on the cross-index plat and is County Official
assigned page No. 622, in book No	Clean L. Vaughn, by Setts Beel,
	Cross Index No X 2/ To 34/ P 2/2

• • and the second s **(**)