2. Description of evid found, note discrepancies in the record, state method of esta corners.

- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner C-N 1/16 Section 10 T. 35 N. R. 27 W. P.M.M. Lincoln


There is no survey or corner recordation on file for this corner.

FOUND
There was no evidence of a monumented corner found.

CORNER PERPETUATION

At the corner point:

Set a 3/4" x 30" aluminum rod with a 3 1/4" diameter aluminum cap, approx. 26" in the ground, marked:




from which bearing trees:

A larch, 8 ins. in dia., bears S 04° E, 60.9 ft. dist., mkd. CN 1/16 S10 BT.

A larch, 8 ins. in dia., bears S 680 W, 77.7 ft. dist., mkd. CN 1/16 S10 BT.

Set a galvanized steel post with a survey marker decal and a property boundary decal 2 ft. South of the aluminum cap.

Painted red bands around the bearing trees and painted the scribing. Attached bearing tree signs and attached Survey Monument Signs.



CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief Philip A. Helps certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Recordation Act" (70-22-181, e.g. seq., M.D.A.) Date: 11 /87 4739 S Reg. No. Employer: F & H Land Surveying, Whitefish

10 Office of Clerk and Recorder, County of ____Lincoln_ *Mov 30* day of 1987, record" was filed for record on the _ was noted on the cross-index plat and is assigned page No. book No. .

F - 15 T. 35 NR. 27 W PMM Cross Index No. -

· - corner this sheet