
INSTRUCTIONS



- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

2 of H.E.S. 1135 T. <u>35 N.</u>, R. <u>32 W.</u>, P.M.M. _ Corner_ County

1922, H.E.S. original record by J. F. Pfau: "Place a small stone marked with a cross (x) under a slatestone 30x8x8 ins., 20 ins. in the ground, marked 2 HES 1135 on SW face, and a cross (x) on top for the exact cor. point, from which

A cross (x) on a lodgepole pine tree, 6 ins. dia., bears $824^{\circ}30$ %, 17 lks. dist. A cross (x) on a lodgepole pine tree, 6 ins. dia., bears $824^{\circ}30$ %, 57 lks. dist., each blazed and scribed 2 H.E.S. 1135 BT.

Raise a mound of stone 4 ft. base, 2 ft. high SW of Cor."

II. Found, a set stone, 7x7 ins., 7 ins. out of the ground, marked 2 HES 1135 on the W face (rcd: SW face), from which

A dead pine, 10 ins. dia., bears $S24^{\circ}W$, 11.6 ft. (17.6 lks.) dist., scribing 2 HES 1135 BT is

A snag, 6 ins. dia., bears N68 $^{\circ}$ W, 38.5 ft. (58.3 lks.) dist., scribing BT is visible.

III. Established two new bearing trees:

A larch, 8 ins. dia., bears $N44^{\circ}W$, 34.1 ft. dist., scribed 2 HES 1135 BT. A douglas fir, 16 ins. dia., bears $N43^{\circ}E$, 23.9 ft. dist., scribed 2 HES 1135 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, N30 W, 3 ft.

Magnetic Declination: 20 30' East



