CERTIFIED CORNER RECORDATION
Corner Cor 5 of HES 787 T. 35N R. 25W P.M.M. Lincoln County
1. 1917 HES Original record by R.E. Maurer: Set:
A small stone, marked with a cross (X) under a sandstone 24x12x6 ins., 14 ins. in the ground, marked 5 H.E.S. 787 on the E face and a cross on top for the exact corner point. From which: A Fir, 5 ins. in diam. bears S22*52'E, 38 lks. dist. mkd. with X and scribed 5 HES 787 BT; A Fir, 7 ins. in diam. bears N12*35'W, 16 lks. dist. mkd. with X and scribed 5 HES 787 BT; A mound of earth 4 ft. base, 2 ft. high, E of corner. 1960 BLM Resurvey by D. Cunningham: Found: A Sandstone, 24x16x6 ins., set and mkd. as above. A Fir, 8 ins. in diam., bears S22*52'E, 38 lks. dist., mkd. 5 HES BT (Record); A stump hole bears N12*35"W, 16 lks. dist. with fallen log mkd. X 5 HES 787 BT (Record); Set:
An Iron Post, 30 ins. long, 2½ ins. diam., 26 ins. in the ground, in concrete, with Brass Cap mkd. A Fir, 9 ins. in diam. bears N40°E, 43 lks. dist., mkd. 5 HES 787 BT; A Fir, 11 ins. in diam. bears S38½°E, 38 lks. dist., mkd. 5 HES 787 BT; Bury original stone alongside and rebuild the mound of stone, 3 ft. base, 2 ft. high, E of the IP. 1991 Resurvey by Alvah F. Hughes:
Found: A BLM Brass Cap on 2½ ins. diam. iron pipe, 4 ins. above ground with rock mound, 2 ft. dist. East of Corner, mkd as shown. A Fir, 15 ins. in diam. bears N40°E, 28.1 ft. (42.6 lks) dist., healed face. A stump, S38°E, 23.5 ft. (35.6 lks) dist., no visible scribing. Established: A Fir, 17 ins. in diam. bears S63°E, 13.8 ft. dist. mkd. 5 HES 787 BT; A 6 ft. galvanized steel guard post with LSM & PB decals, North, 3 ft. dist.
2. Found: A BLM Brass monument, 3½ ins. in diam., 4 ins. out of ground surrounded by a mound of stone, mkd. as shown; A Douglas Fir, 17 ins. in diam., bears N40°E, 28.10 ft. dist., with a well healed face; A Douglas Fir, 22 ins. in diam., bears S63°E, 13.80 ft. dist., with a well healed face; A Steel post, bears North, 3 ft. dist. with Boundary and Location tag.
3. Restacked and painted a mound of stone around monument. Repainted blazes and rings on all BTs. T35N R25W COR 5 HES 787 TR B 1960
MAGNETIC DECLINATION - 16' EAST
StI Post North, 3' 17" D Fir LAWRENCE A. CLAHE Certify the information shown have been to make from the configuration of the configura
Office of Clerk and Recorder, County of Lincoln This "corner 229566 BOOK: CCR CCER'S PAGE: 11636 Pages: 1 record" was filed for re STATE OF MONTANA LINCOLN COUNTY RECORDED: 11/16/2010 9:06 KOI: CCER'S was noted on the cros TAMMY D. LAUER CLERK AND RECORDER book No. FEE: \$0.00 BY: SEASON SANDPOINT, ID. 83860, 5 HES 787 Cross Index No. 5009 T. 35N R. 25W PMM
Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors © corner this sheet

Car Service Se .

.