CERTIFIED LAND CORNER RECORDATION

SECTION 31 TWP. 35 N., R. 25 W., M.P.M.

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

West $\frac{1}{4}$ Corner of Sec. 30 - found a Standard Brass Cap Monument East $\frac{1}{4}$ Corner of Sec. 31 - found a Standard Brass Cap Monument

SEE OTHER SIDE

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: Oct. 1973

SEE DIAGRAM ON OTHER SIDE

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SEE DIAGRAM ON OTHER SIDE

Surveyor's Seal	Jack H. Ninneman	DIAGRAM OF CORNER:
	certify that the information shown herein is true and correct.	N.
	Jack H. Rimeman	4 1/16 Cor.
	Signature of Ground Party Chief	
	I, Jack W. Ninneman	7 31
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	T 35N R 25W
	Jack W. Dinneman	● = Corner recorded in the sheet
	Signature of Surveyor	1
	Montana License # 5	534 E.S.
	Registration Number	•

Office of Clerk and Recorder, County of South Mer.

This "corner record" was filed for record on the 2 day of Strendard 19 day of 19 day of Strendard 19 day of Strendard 19 day of County Official

FORM 125-41483

Cross Index No. W-/ T. 35 R. 35 Mer.

RECORDATION OF MONUMENTS SET IN SECTION 31 TWP 35 N., R. 25 W., M.P.M.

TWP. 35 N., R. 26 W., M.P.M.
TWP. 35 N., R. 25 W., M.P.M.

Found a standard Brass Cap Monument set by B.L.M. for West $\frac{1}{4}$ Corner of Section 30 at 5294.2 feet North of West $\frac{1}{4}$ Corner of Section 31 set by others.

*2 STEEL PIN

Sec. 36

STEEL PIPE

SEC. 31

5192.33' N89*35'20"W

BRASS CAP

#I SET A STEEL PIPE FOR War SEC. 31 AT FENCE CORNER
WITH 1960 LOCATION POSTER Set by others and accepted by contiguous owners.

#2 SET A STEEL PIN FOR W 1/16 N SEC. 31 FROM WHICH A
LOCATION POSTER ON A CORNER FENCE POST LIES NORTH
7 FEET AND EAST I FOOT. The northwest corner of subject
Section 31 fell in a mill yard
and has been destroyed—accordingly
1/16 Corner—designated #2 herein—
was set ON LINE between the W \(\frac{1}{4} \)
Corner of Section 31 and the W\(\frac{1}{4} \)
Corner of Section 30 at single
proportionate distance.