CERTIFIED CORNER RECORDATION

Corner W 1/16 Sections 25 & 36 T. 35N R. 26W P.M.M. LINCOLN County

G.L.O. Record:

This interior section subdivisional corner was never set by G.L.O. or other original government survey, but its position can be calculated by dimensions shown on the official government plat for this township.

Subsequent Record:


Certificate of Survey No. 2609, Dawn Marquardt, 7328S. Certificate shows that a 5/8" rebar with plastic ID Cap was set at the corner position. Proportional methods used to establish the corner position were not shown.

Evidence Found and New Monumentation Established:

At the calculated position for the corner, as established by proportionate measure and as shown on the attached section subdivisional diagram, I find a 5/8" diameter rebar with a yellow plastic cap stamped "7328S MARQUARDT".

I replace the rebar and cap with a Berntsen flared base monument (model #A1NBF30), which consists of a 2-3/8" diameter by 30" long flared aluminum pipe with a magnet and 3-1/4" diameter aluminum cap attached to the top, stamped as shown in detail below. I bury the rebar inside the monument pipe. Top of installed monument is flush with ground surface.

Section Subdivision Section 36, Township 35 North, Range 26 West





SKETCH OF CORNER

CERTIFICATION 4740LS Employer Smith Surveying & Consulting

Office of Clerk and Recorder County of Lincoln This "corner 190085 BOOK: CCR CCER'S PAGE: 10886 Pages: 1	Sec.	36		
record" was filed for rect state of montana Lincoln county	\Box			
was noted on the cross- RECORDED: 12/05/2005 2:10 KOI: CCER'S CORAL M. CUMMINGS CLERK AND RECORDER				
book No. FEE: \$0.00 BY: Lawred Leune Congress of the Surveying 1131 South Mais, P.O.Box 7323, KALISPELL, MT	+	\dashv		
Cross Index No. <u>V-22</u> T. <u>35N</u> R. <u>26W</u> PMM				
Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors	•=cor	rner t	his s	sheet

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

