L:\CUENTS\Department of State Lands\Fortine\Drawings\Corner Recors.

CERTIFIED CORNER RECORDATION

Corner	C-W 1/16	Section 36	т	35N	R	26W	P. M. M	LINCOLN	. County

G.L.O. Record:

This interior section subdivisional corner was never set by G.L.O. or other original government survey, but its position can be calculated by dimensions shown on the official government plat for this township.

Subsequent Record:


Certificate of Survey No. 2609, Dawn Marquardt, 7328S. Certificate shows that a 5/8" rebar with plastic ID Cap was set at the corner position. Proportional methods used to establish the corner position were not shown.

Evidence Found and New Monumentation Established:

At the calculated position for the corner, as established by proportionate measure and as shown on the attached section subdivisional diagram, I find a 5/8" diameter rebar, no cap, bent over.

I replace the rebar and cap with a Berntsen flared base monument (model #A1NBF30), which consists of a 2-3/8" diameter by 30" long flared aluminum pipe with a magnet and 3-1/4" diameter aluminum cap attached to the top, stamped as shown in detail below. I bury the rebar inside the monument pipe. Monument is on the south edge of a farm access road. Placed small collar of rock around cap, which is flush with ground.

Section Subdivision Section 36, Township 35 North, Range 26 West



SKETCH OF CORNER

Michael Smith Surveying & Consulting

Office of Clerk and Recorder, Co	unty of Lincoln	This "corner	Sec.	38		
record" was filed for recoi stat	190086 BOOK: CCR CCER'S E OF MONTANA LINCOLN COUNTY	PAGE: 10887 Pages: 1				
was noted on the cross-ir RECO	RDED: 12/05/2005 2:12 KOI:	CCER'S				
	\$0.00 By	P.O. BOX 7323, KALISPELL, MT	uf			
	Cross Index No. X-22	T. 35N R. 26W PMM			1	
Adopted July 1, 1981, Monta	na Board of Professional Engine	ers & Land Surveyors	•=c	orner	this	sheet

