CERTIFIED CORNER RECORDATION

SE 1/16 Sec. 15 T 36 N. R. 26 W. P.M.M. LINCOLN County

Record: 1997 Certificate of Survey #2523 by Dawn Marquardt: Subdivides the SE 1/4, section 15, creates Parcel "A" in the S 1/2 SE 1/4 and establishes the CS 1/16. A 5/8 in. diam. x 24 in. long rebar with a yellow plastic cap stamped 7328S was set at the position for the CS 1/16.

2000 Subdivision Plat of Glenwood Estates #6373 by Dawn Marquardt: Subdivides the E 1/2 S1/2 Parcel "A", section 15, creates Lots 1 and 2 and establishes the SE 1/16. A 5/8 in. diam. x 24 in. long rebar with a yellow plastic cap stamped 7328S was set at the position for the SE 1/16.

2001 Certificate of Survey #3061 by Dawn Marquardt: References the SE 1/16.

- Found a 5/8 in. diam. rebar, 6 ins. above ground, with a yellow plastic cap marked MARQUARDT 7328S.
- Accept the position of the found Marquardt rebar as the true position for the SE 1/16. III. Removed the yellow plastic cap and replaced it with a 3 1/4 in. diam. aluminum cap marked as shown:

T36N R26W SE 1/16 **S15** 13769LS 2002

The new bearing trees:


A fir, 8 ins. diam., N11°E, 25.5 ft., marked X BT. A fir, 10 ins. diam., N64°E , 33.2 ft., marked SE 1/16 S15 BT.

Set a 6 ft. galvanized steel guard post 3.0 ft. north and west, with Property Boundary and Land Survey Monument decals attached. Attached Bearing Tree and Land Survey Monument signs to the bearing trees. Painted red bands around the bearing trees.

Date of Fieldwork: 11/7/2002 Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 20° East assumed


Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211



SKETCH OF CORNER

NOT TO SCALE




Lincoln Office of Clerk and Recorder, County of This "corner record" was filed for record on . was noted on the cross-index plat and, is assigned page No

book No. County Official

Cross Index No. <u>M-16</u> J. <u>36N. R. 26W.</u>

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



· corner this sheet