

## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.


## • CERTIFIED CORNER RECORDATION

Corner 1/4 cor. between Sec. 15 & 22 T. 36 N R. 26 W P.M.M. Lincoln County

Found BLM brass cap

See C. of S. No. 915 for adjacent corners.

14" doug. fir



SKETCH OF CORNER

### CERTIFICATION

I, \_\_\_\_\_  
certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Macquardt

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

D.K. Macquardt  
Signature of Surveyor & Seal

Date: 7-15-81 Reg. No. 2089ES


Employer: \_\_\_\_\_

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 17<sup>th</sup> day of 1981, was noted on the cross-index plat and is assigned page No. 1105 in book No. 1

Claudia L. Vaughn, by Betty Bell  
County Official Deputy

Cross Index No. N-15 T. 36 N R. 26 W P.M.M.

Sec. 22



• - corner this sheet