

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

• CERTIFIED CORNER RECORDATION

Corner Sec. Cor. Sections 12 E 13 T. 36 N R. 27 W P.M.M. Lincoln County
 Sections 7 E 18 T 36 N R 26 W

Record: Set a limestone 15x12x8 ins. 10 ins. in the ground marked with 2 notches on N & 4 notches on S edges.

Dug pits for Rms.

Found aluminum monument set by Harges '2520's'
 Accepted as corner.

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

DK Marquardt

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

DK Marquardt
 Signature of Surveyor & Seal

Date 7-10-81 Reg. No. _____

Employer: _____


SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the 12th August day of 1981, was noted on the cross-index plat and is assigned page No. 1201, in book No. 1

John L. Vaughan by Betty Bell
 County Official Deputy

Cross Index No. J-25 T. 36 N R. 27 W PMM
J-1 T 36 N R 26 W

Sec. 12



• - corner this sheet