
INSTRUCTIONS



- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner 4 coc.	Section 7	T. <u>3⊆ю</u>	R.26W P.M.M. Lincoln	County
	Section 12	T 36N	RETW	

Record: Set a limestone 16x 12 x 10 in & Ilins. In the ground from Which !.

a pine 15" diam. bears. 580°C. 1421ks. a pine 14" diam. bears 955°W. 861ks.

No evidence of original corner found. Set brass cap at fence corner See C.ofs No. 821 for adjacent corners

