#### INSTRUCTIONS

- vidence found, note discrepancies in the second, state method of establishing lost or obliterated
- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
  Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

11 a corner。 T. <u>36N</u> R. <u>26W</u> \_\_P.M.M. <u>Lincoln</u> Corner\_ County

### **RECORD:**

GLO: Set quartzite boulder 16x14x12", 11" in ground for 4 Sec. Cor., marked 뉳 on N. face.

# FROM WHICH:

A pine 9" diam. bears N. 20° 30'W. 65 LKS. Dist., marked  $\frac{1}{4}$  S.B.T. A fir 8" diam. bears S. 13° E., 14 LKS. Dist., marked  $\frac{1}{4}$  S.B.T.

FOUND: The position of this corner fell in a clearcut area. Approximately 3/4 of one crew day was spent searching for evidence of this corner, no evidence was found and the corner was determined lost.

By single proportion a 2½" x 30" Forest Service aluminum pipe approximately 24" in ground with an aluminum cap marked as shown with a stone collar.

# FROM WHICH:

A 4" fir bears S28W, 56.4 feet, inscribed S 14 BT. A 2" pine bears N64E, 51.7 feet, inscribed S 11 BT.





