## DISTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing

- 3. Description of monument and accessories set to perpetuate the corner position.
  4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, topography ties, position of accessories, etc.
  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner <u>CS 1/16 Sec. 14</u> R. 26W P.M.M. Lincoln 36N County


RECORD: None available.


FOUND: A 2" iron pipe 8" above ground, bears NO8E, 6.7 feet\from set corner.

SET: A 2½" x 30" Forest Service aluminum pipe approximately 24" in ground with an aluminum cap marked as shown with a stone collar.

## FROM WHICH:

A 12" larch bears N65E, 37.9 feet, inscribed CS 1/16 BT. A 12" fir bears S79W, 25.6 feet, inscribed 1.16 BT.





certify that this Corner Record correctly represents work performed or under by direction in compliance with th 12" fir Date: 1-27-82 Reg. No. 5612-5 **SKETCH OF CORNER** Office of Clerk and Recorder, County of LINCOLN . This "corner record" was filed for record on the MARCH . day of 19  $\gg$ 

ELEANOR L. VAUGHN BY

County Official

Betty L

· corner this sheet

Confe

T. 36 N R. 26 W PMM

was noted on the cross-index plat and is assigned page No.

book No. 🗓