INSTRUCTIONS

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch exampl topography ites, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

R. 26W Corner NE 1/16 Con T. 36N P.M.M. Lincoln County


Record: None available

By section subdivision a standard Forest Service 2½ x 30 inch

aluminum monument with a 3 inch aluminum cap stamped as shown:

From Which: A 11 inch fir bears S48E, 13.6 feet, marked NE 1/16 B.T. A 13 inch larch bears S57W, 15.0 feet, marked NE 1/16 B.T.


A location poster bears N36W, 8.5 feet



book No. 1



· corner this sheet



County Official

T. 36N R. 26W PMM

0-20