INSTRUCTIONS

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, cor topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner CN 1/16 Sec. 23 T. <u>36N</u> _R. _26W_ P.M.M. __Lincoln County

RECORD: None available.

FOUND: A post with Forest Service location poster, bears N26W, 10.0 feet


from set cap.

SET: A 2½" x 30" Forest Service aluminum pipe approximately 26" in ground

with an aluminum cap marked as shown, surrounded with stone collar.

FROM WHICH:

A 6" pine bears N33E, 5.5 feet, inscribed XBT. A 7" pine bears S12E, 9.9 feet, inscribed N 1/16 BT. A location poster bears N37E, 10.3 feet.





corner this sheet

	SURVE SURVE
SKETCH OF CORNER	CERTIFICATION I. JAMES WREED certify the information shown herein is true and correct. Signature Ground Party Chief I. certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation April (70-22-101, et seq., M.D.A) Signature of Surveyor & Seal Date: 27-82 Reg. No. 56/2-5 Employer: USFS
was noted on the cross-index plat and is assigned page No	036, in