## INSTRUCTIONS

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, core topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

CE1/16 Sec. 34 County

RECORD: No record of corner on file.


FOUND: Nothing to show evidence of a previously monumented corner.

A  $3\frac{1}{4}$  in. aluminum cap on a 30 in. long aluminum pipe, approx. 2 ins. above ground, surrounded by a stone collar and mkd. as shown.

from which

A fir, 8 ins. diam., bears S.46°W., 23.6 feet dist., scribed "1/16 BT".

A fir, 6 ins. diam., bears  $N.46^{\circ}W.$ , 17.8 feet dist., scribed "1/16 BT".





CERTIFICATION 6" FIR James W. <u>Hill</u> <u>Thomas</u> certify that this Corner Record correctly represents w by me or under by direction in compilan Recordation Act." (70-22-191, et seq., M.D.A.) Date 10/20/83 Reg. No.5612S

SKETCH OF CORNER Employer:		
Office of Clerk and Recorder, County ofLINCOLN	. This "corner	Sec. 34
record" was filed for record on theNovember 29	_ day of 1983	
was noted on the cross-index plat and is assigned page No. $\frac{2382}{100}$		
book No Janeth Siagel by Bet	ty L. Conces	
CountyOfficia	all deputy	

· - corner this sheet