## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Record: Set a post, from which:

A 10" Tamarack bears S30°E 22 links A 12" Tamarack bears N73°W 38 links

Found: Rebar 1' East of fenceline and bearing tree stump in SE Quadrant.

Rebar found to be in the proper location for the 1/4 corner.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Nov. 1975

DIAGRAM OF CORNER.

Date of works.

"E.S. 2989 " Tay IN

12" Fir

Fd. 3/4" Rebar

"E.S. 2989 Tay IN 14" Fir

"E.S. 2989 Tay IN 14" Fir

Scribing Visible

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey Number 152

Surveyor's Seal	I. S.R. Smith
	certify that the information shown herein is true and N. 736 N correct.
	SR Smith S18
	Signature of Ground Party Chief
	Dean K, Marquardt R 26 W
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.
	Signature of Surveyor = Corner recorded on the sheet

Registration Number

Office of Clerk and Recorder, County of Line of Line of January 19.74 was noted on the cross-index plat and is assigned page No. 425, in book No.

Cross Index No. No. 125-41808

Cross Index No. No. 125-41808