INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. ______ P.M.M. CW 1/16 OF S33 Lincoln Corner_ _County No previous record.

No evidence found.

III. At the calculated position, set a 3/4 in. diam., 30 ins. long, alum. rod 24 ins. in the ground with alum. cap mkd. as shown.

> w 1/16 C ----C \$33 9008LS 1992

From which

A pine, 20 ins. diam., bears N8 E, 35.7 ft. dist., mkd. CW 1/16 S33 BT. A pine, 6 ins. diam., bears N70 $^{\circ}$ E, 11.4 ft. dist., mkd. CW 1/16 S33 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, South, 3 ft. Magnetic Declination: 20 East



20"PINE

CERTIFICATION Kevin A. Todd certify the information shown herein is true A Toll e Ground Party Chief Ronald A. Pearson certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the interest of Act." (70-22-101, et seq., M.C.A.) Q D. T Signature of Surveyor & Seal 10/1/92 Reg. No. 9008 LS Employer: U.S. FOREST SERVICE

SKETCH OF CORNER

Office of Clerk and Recorder, County of .. _ . This ''corner record" was filed for record on __ was noted on the cross-index plat and is assigned page No. . oral M. book No. _ County Official

Cross Index No. -

Sec. 33

· corner this sheet