


INSTRUCTIONS

1. Original and/or subse. record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing, lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography (tes, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

- CERTIFIED CORNER RECORDATION

Corner Section Corner - Sections 23, 24, 25, 26 T. 36N R. 27W P.M.M. Lincoln County

Found BLM brass cap



CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Maquardt
certify that this Corner Record correctly represents work performed
by me or under my direction in compliance with the "Corner
Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 7-9-81 Reg. No. 5282ES

Employer: _____


SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner
record" was filed for record on the 17th July day of 1981,
was noted on the cross-index plat and is assigned page No. 1112, in
book No. 1

Clarence L. Vaughn, Jr. Deputy
County Official

Cross Index No. R-21 T. 36N R. 27W P.M.M.

Sec. 23



• - corner this sheet