Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner Sec. Cor 5,6,7 &8 T. 36N R. 27W P.M.M. Lincoln

Record'.

Set a post 4' long, 24" in the ground from which:

pine 14" dia. bears 10.270.30'E. 84 1ks

5, 13° E. 140 lks pine 32" dia. bears

5.40°W. 103 1Ks 8" dia bears pine

Found original BT stumps

Set brass cap

book No. .

See C.of S. No. 541 for adjacent corners

5" pine Quisecu (Razu	CERTIFICATION
3/ 2989ES	Signature Ground Party Chief D.K. Maga Cacch certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-10), et seq., M.D.A.) Signature of Surveyor & Seci Date: 1-6-81 Reg. No. 1985 E.S.
10 Pine & SKETCH OF CORNER	Employer:
Office of Clerk and Recorder, County of	Sec. 5 Lay day of 198%

_ т. <u>36 Ю</u> г. <u>эт ш</u> РММ

County Official

corner this sheet